
InnovairFlex D4120A Product Enhancement

Dear Valued Customer,

System Sensor is pleased to announce that starting September 14, 2012, all InnovairFlex™ D4120A, D4SA, and D4P120A duct smoke detectors will begin shipping with some key product enhancements. These enhancements include the following:

- The InnovairFlex D4120A 4-wire duct smoke detector will have a new smoke clearing feature allowing the auxiliary contacts to open upon reset enabling the fan, which will blow the remaining smoke out of the sensing chamber after smoke testing, allowing the detector to go into a full reset.
- A new cover will begin shipping on the sensor component of the product. This new cover will make the detector more resistant to dust and reduce maintenance when installed in dirty or dusty environments. This is not however a substitute for a regularly scheduled preventative maintenance plans.
- A software update will be implemented to increase the length of the LED blinks on the power board allowing them to be seen more easily in challenging visual conditions, such as, outdoor rooftop applications.
- The Maintenance Condition Signal indicating that the detector is dirty and needs to be cleaned or replaced will become a localized LED indication on the detector and remote test accessory only. A Maintenance Condition Signal will no longer be sent to the panel, all other Alarm and Trouble signals shall continue to operate as before.

Should you require any assistance or have any further questions please contact me.

Sincerely,



Philip Anderson
National Sales Manager
System Sensor Canada

